




Service Tips

Dual Zone 18+18 Combination

There is a misprint in the current 2016 Fujitsu Catalog that shows a kit is required for an 18+18 combination on the AOU36RLXFZH. However, this kit is only required for the AOU36RLXFZ1. With the AOU36RLXFZH, the 18+18 combination was included in the base of design eliminating the need to upsize the piping.



AOU36RLXFZ1 / AOU36RLXFZH						
		18*	18*			36
		7	7	15	-	29
		7	7	18	-	32

The optional kit "K9FZ1818 is necessary for dual zone system "18+18" on the AOU36RLXFZ1 only.