




Service Tips

Communication Check - HFI Models



All positive readings would indicate a problem with outdoor unit and testing of the PCB will be required.

All negative readings would indicate a problem with indoor unit and replacement of the indoor PCB may be required.

Disclaimer: